

C39 METALS/ANIONS/Cyanide IN SOIL (TCLP)

1.0 Sample Reception

- 1.1 All breakages and shortages must be reported within 24 hours of sample receipt.
- 1.2 Store samples at $4\pm2^{\circ}$ C and in the dark upon receipt. Leach samples as soon as possible after receipt.
- 1.3 Check that all the parameters for which you are registered are correctly identified in the PTC portal.
- 1.4 Inquiries regarding samples and their shipment may be directed to:

PT Non-conformances
Information and Quality Management
Environment and Climate Change Canada
fav. ODE 776, 2016

fax: 905-336-8914

email: ec.ptnc.ec@canada.ca

cc: PT Canada, Program Officer email: <u>programofficer@PTcanada.org</u> cc: Ken Middlebrook, PT Canada email: <u>kmiddlebrook@PTcanada.org</u>

Inquiries should be made by email if possible. Use the Nonconformance Form (see reverse) when sending a fax. When reporting damage upon receipt, please provide a picture of the damaged samples. Please include your PT Canada laboratory number on all correspondence.

2.0 Sample Analysis

- 2.1 Refer to PAR02 Catalogue for approximate concentration range.
- 2.2 Proceed with testing using the routine analytical method identified in your PT Canada application. Separation and particle size reduction is not required. Proceed under the assumption that the samples are 100% solids.

3.0 Reporting Results

- 3.1 Results must be reported by midnight of the study deadline in the PTC portal.
- 3.2 Report results using the units in the PTC portal.

4.0 Safety

4.1 The PT samples are designed for use by laboratory professionals familiar with environmental samples and potentially hazardous materials.

PT SAMPLE NON-CONFORMANCE FORM

Attn: PT non-conformances	Study Number:	
ENSURE THAT SAMPLES	S RECEIVED MATCH REPORT FORMS	
1 - Laboratory Information		
Contact Name:		
<u>Laboratory Name</u>		
<u>Laboratory Address</u>		
Contact Telephone #		
Contact Facsimile #		
Contact e-mail:		
2 - Sample Details		
Date & Time of Arrival(YYYY,MM,DD,HH:MM):		
Tracking Number:		
Test Groups Received (e.g. C1, C2 etc.):		
Number of Boxes:		
3 - Description of Nonconformance		
4 - Requested Action		